

Public Works Report May 2018

12" Transmission Main Preparations: To date our crew has taken delivery of 4000 feet of HDPE water main. It requires two excavators to unload the 40 foot long packs of pipe. Our crew had to stop tree clearing operations along the pipe route to attend to spring cleanup and road repairs.



Spring Cleanup: Our crew has been busy at all our facilities, playgrounds and beach areas cleaning up the massive amount of winter debris that has collected from storms like the late October wind storm that knocked out power for days and numerous storms since then.

Water Main Breaks: Our crew repaired to serious main breaks this past month. One repair on Beech Circle was discovered late in the day causing the repair to go well into the night. Our crew finished the job by headlight and flashlight. The second break occurred on a sunny Saturday afternoon. Four of our crew dropped what they were doing on their day off and hauled in the heavy equipment and repaired the extremely bad leak before the sun went down.



Equipment Repairs: Due to abnormal tire wear we had to send our International 10 Wheeler to have the rear suspension rebuilt and the front end aligned. Surprisingly it was the first time it needed to be done since it was new in 2004. It will be finished this week and will cost about \$2,500.

Water Production for April 2018 was 13 Million Gallons.